



3520C Headstock Assembly

Product Images



Description

Index Number	Part Number	Description	Size	Qty
1	6294725	Spur Center	MT2	1
2	6294736	Faceplate (includes #17 and 102)	1-1/4-8, Ø 3"	1
3	6295796	Nylon Insert Socket Set Screw	1/4"-20 x 3/8"	4
4	3520C-104	Spindle		1
5	F014007	Flat Key, Dbl Rd Hd	8x8x40mm	1
6	F014008	Flat Key, Dbl Rd Hd	8x8x80mm	1
7	BB-6207ZZ	Bearing	6207ZZ	2
8	3520B-208	Bushing		1
9	JWL1642-174	Locking Collar		1
10	TS-0270021	Socket Set Screw	5/16"-18 x 5/16"	3
11	3520C-111	Spindle Pulley		1
12	6077228	Belt	260J-10V	1
13	F006048	C-Retaining Ring, Ext	S-22	1
14	SR-6P3	Strain Relief	SR-6P3	2
15	TS-2246252	Socket Head Button Screw	M6-1.0x25	2
16	JWL1640EVS-125	Sensor with Cable		1
17	6295796	Nylon Insert Socket Set Screw	1/4"-20x3/8"	2
18	3520B-273	Socket Set Screw	#10-24x1"	1
19	JWL1642-127	Machine Screw	M3-0.5x10	4
20	F009669	Socket Head Button Screw	#10-24x3/8"	2
21	3520C-121	Bracket		1
22	TS-0560071	Hex Nut	#10-24	2
23	3520C-123	Spindle Encoder PCB Assembly		1
24	3058001	Clamp Bolt		1
25	3092095	Clamp		1
26	6520009	Hex Nylon Lock Nut	5/8"-11	1
27	3520C-127	Lock Handle Assembly		1
28	TS-0271031	Socket Set Screw	3/8"-16 x 3/8"	2
29	6095038	Bushing		1
30	3520C-130	Spindle Lock Plunger Seat		1

31	3520C-131	Headstock Eccentric Shaft		1
32	3520B-275	Spindle Comparator Spur Center		1
33	6644005	Plunger Retainer		1
34	TS-0209061	Socket Head Cap Screw	3/8"-16x1-1/4"	2
35	TS-0720091	Lock Washer	3/8"	3
36	3064711	Lathe Guard Bracket		1
37	3520C-137	Headstock Casting		1
38	3520C-138	Spring		1
39	3520C-139	Spindle Lock Pin		1
40	3520C-140	Cover Plate (includes #94)		1
41	3520C-141	Control Box Assembly		1
42	F010675	Flat Head Socket Screw	#10-24x3/8"	2
43	LM000303	Speed Label, 3520C		1
44	6295717	Knob	M8	1
45	3520C-145	Access Door (includes #43 and 101)		1
46	TS-1490021	Hex Cap Screw	M8-1.25x16	1
47	F010878	Flat Head Socket Screw	M3-0.5x10	2
48	3520C-148	Magnet		2
49	BB-6206VV	Bearing	6206VV	1
50	6864006	Bearing Lock Washer		1
51	6549006	Bearing Nut		1
52	3271081	Handwheel		1
53	3719189	Motor Sheave		1
54	3520C-154	Spindle Index Pin		1
55	3520C-155	Spring		1
56	F006086	C-Retaining Ring, Ext	S-9	1
57	3520C-157	Cushion		1
58	TS-1540071	Hex Nut	#10-24	9
59	JWL1440-141	Strain Relief	M16	3
60	SR-PG13.5	Strain Relief	PG-13.5	1
61	SR-6P3	Strain Relief	SR-6P3	1
62	TS-081C062	Phillips Pan Head Machine Screw	#10-24x1"	4
63	JWL1642-169	Braking Resistor		1
64	F000648	Phillips Pan Head Machine Screw	#10-24x1/4"	1

65	3520C-165	Inverter		1
66	JWL1640EVS-163	Inverter Lower Box		1
67	JWL1640EVS-161	Inverter Upper Cover		1
68	TS-081C062	Phillips Pan Head Machine Screw	#10-24x1"	2
69	TS-081C052	Phillips Pan Head Machine Screw	#10-24x3/4"	1
70	F010749	Flat Head Socket Screw	3/8"-16x3/4"	4
71	3520C-171	Motor Mount Plate		1
72	TS-0680041	Flat Washer	3/8"	1
73	TS-0209061	Socket Head Cap Screw	3/8"-16x1-1/4"	1
74	F014009	Flat Key, Dbl Rd Hd	3/16"x3/16"x2-1/2"	1
75	LM000302	Motor Label		1
76	3520C-176	Motor	2HP	1
	3520C-176JBC	Junction Box Cover		1
	3520C-176MF	Motor Fan		1
	3520C-176MFC	Motor Fan Cover		1
77	TS-0680041	Flat Washer	3/8"	1
78	3520C-178	Lock Handle	3/8"-16x1"	1
79	6294744	Face Plate Wrench		1
80	3520C-180	Motor Cord		1
81	3520C-181	Signal Cord (Inverter box to Encoder PCB box)		1
82	6294754	Knockout Rod Assembly		1
84	TS-0733031	Lock Washer Ext Tooth	#10	1
85	3520C-185	Sensor Collar		1
87	TS-0267021	Socket Set Screw	1/4"-20x1/4"	2
88	3520C-188	Knob		1
89	TS-2244102	Socket Head Button Screw	M4-0.7x10	1
90	TS-0253031	Socket Head Button Screw	#10-24x1/2"	19
91	AP2-16	Spring Pin	Ø6 x 25mm	1
93	F009669	Socket Head Button Screw BO	#10-24x3/8"	3
94	3520C-194	Spindle Lock Label		1
95	3520C-195	Fixed Plate		1
96	3520C-196	Sensor Bracket		1
97	3520C-14110	Signal Cable (Remote Box to Inverter)		1
98	TS-2283102	Pan Head Screw	M3-0.5x10	2

99	3520C-199	Spindle Lock Guard		1
100	3520C-1100	Sleeve		1
101	3520B-294	Warning Label – Belt Adjustment		1
102	4224B-1124	Warning Label – Faceplate		1
103	3520C-1103	Main Switch (includes #104)		1
104	TS-1512021	Flat Head Screw	M4-0.7x12	4
105	3520C-1105	Main Switch Box		1
106	3520C-1106	Power Cable (Main switch box to Inverter, not shown)		1
107	3520C-1107	Strain Relief, Motor (not shown)	7N-2	1
108	JWL1015-172	Clamp		1

Additional Information

Stock Number	1353001-1
--------------	-----------

Products in this set